

PREMIER DODGE CHRYSLER JEEP OF LEBANON, LLC

600 Pleasant Grove Rd.
Mount Juliet, TN 37122
(615) 288-8525



SERVICE DEPARTMENT HOURS
7:30 a.m. to 6:00 p.m.
Monday - Friday
8:00 a.m. - 4:00 p.m. Saturday

R/O Open Date	R/O Number
11/30/17	6091950/1
R/O Close Date	Status
12/20/17	Pre-Invoice
Mileage In	Mileage Out
14361	14365
Service Advisor / Tag #	
JONATHAN/345	

THORNES EXCAVATING CO LLC
624 OLD HORN SPRINGS RD
LEBANON, TN 37087-1811

Work Phone	Vehicle Identification Number	
	1C6RR7FT0HS584639	
Home Phone	Delivery Date	In-Service Date
615-444-5142	11/18/16	11/18/16
Body	Color	License Number
TRADESMAN 4X4 QUA	FLAME RED	

Year: 2017 Make: RAM Model: 1500 (5.7L) Body: TRADESMAN 4X4 QUA Color: FLAME RED License Number: D5918

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

Email: erict@tec63.com

#1 - MISC: MISCELLANEOUS
BOTH REAR TIRES CONTINUOUSLY LOSE AIR THROUGH THE VALVE STEMS
Tech: WILLIAM GARARD (327)
Installed 68249197AA :SENSOR: TIRE PRESSURE Qty: 1 Warranty
REPALCED TPMS SENSOR Warranty

#2 * MISC: MISCELLANEOUS
ADDED OPERATION
LEFT REAR TIRE LOSES AIR
Tech: WILLIAM GARARD (327)
Installed 68249197AA :SENSOR: TIRE PRESSURE Qty: 1 Warranty
REPLACED TPMS SENSOR Warranty

#15
Kevin

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto"

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

PREMIER DODGE CHRYSLER JEEP OF LEBANON, LLC

600 Pleasant Grove Rd.
Mount Juliet, TN 37122
(615) 288-8525



SERVICE DEPARTMENT HOURS
7:30 a.m. to 6:00 p.m.
Monday - Friday
8:00 a.m. - 4:00 p.m. Saturday

R/O Open Date	R/O Number
11/05/18	6108217/1
R/O Close Date	Status
11/05/18	Pre-Invoice
Mileage In	Mileage Out
27283	27283
Service Advisor / Tag #	
Albee Holt/855*W*	
Vehicle Identification Number	
1C6RR7FT0HS584639	
Delivery Date	In-Service Date
11/18/16	11/18/16
Color	License Number
FLAME RED	

THORNES EXCAVATING CO LLC 624 OLD HORN SPRINGS RD LEBANON, TN 37087		
Year	Make	Model
2017	RAM	1500 (5.7L)
D5918		

Work Phone	Home Phone	Body
	615-444-5142	TRADESMAN 4X4 QUA

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

Email: erict@tec63.com

#1 - RECALL: RECALL
RECALL / CSN 1 U05: CUSTOMER SATISFACTION
NOTIFICATION U05 - AUTOPARK FUNCTIONALITY**
Caused by
COMPLETE
Tech: ABEL ROJAS VALLEJO (321) Warranty

#2 - RECALL: RECALL
RECALL / CSN 2 U61: SAFETY RECALL U61 - REPROGRAM
POWERTRAIN CONTROL MODULE**
Caused by
COMPLETE
Tech: ABEL ROJAS VALLEJO (321) Warranty

#3 - 9090: EXPRESS LANE INSPECTION
MULTI-POINT INSPECTION (ACCORDING TO MAINTENANCE
INTERVAL)
Sub Total: .00

#15
Kevin

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."	LABOR	.00
	PARTS	.00
	DEDUCTIBLE	.00
	SUBLET	.00
	SHOP SUPPLIES	.00
	HAZARDOUS MATERIALS	.00
	SALES TAX OR TAX I.D.	.00
	SPECIAL ORDER DEPOSIT	.00
	DISCOUNTS	.00
	TOTAL DUE	.00

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>15</u> MAKE <u>RAM</u> MODEL <u>171500 4x4</u> SERIAL # <u>DAVE</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	---

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE <u>12-7-18</u> DATE COMPLETED <u>12-10-18</u> MECHANIC <u>Charles</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
---	---

PROBLEM: Front dent

REPAIRED: replaced Front Fascia

PARTS: Front Fascia 147.⁰⁰ Premier Dodge

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 15

MAKE Ram

MODEL 17' 1500

SERIAL # ~~XXXX~~ JETT M.

HOUR METER _____

MILES 34K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____

MECHANIC JAMES

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: set up for Jett M.

REPAIRED: Tri fold cover install
Power inverter

PARTS: Arma Flex ~~1,148~~ ⁰⁰ Chuck's Truck
1500 watt Power inverter, 217.00 Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 15

MAKE RAM

MODEL 17' 1500 4X4

SERIAL # _____

HOUR METER _____

MILES 35k mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-24-19

MECHANIC I B5

JOB NAME/LOCATION

JOB NUMBER

I B5

PROBLEM: bad battery

REPAIRED: replaced battery

PARTS: MTX 94R 206.94 I B5

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0015</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17 1500 4X4</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>BJ</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-1-19</u>	MECHANIC <u>All</u>
PROBLEM: <u>safety light</u>		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
REPAIRED: _____			
PARTS: <u>light</u> <u>329.⁰⁰</u> <u>Truckers lighthouse</u>			

REPAIRED: _____			
PARTS: <u>P265-70 17</u> <u>194.⁷⁵</u> <u>Charlies tire</u> <u>Goodyear</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 17

MAKE Dodge Ram

MODEL 1500

SERIAL # _____

HOUR METER _____

MILES 65000

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 11-26-19 DATE COMPLETED 11-26-19

MECHANIC Bryan

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Service

PARTS: Filter & Oil in stock

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0015

MAKE Ram

MODEL 17 Ram 1500 4x4

SERIAL # JeAM

HOURLY METER _____

MILES 43K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-24-2020

MECHANIC Charlie's Tire

JOB NAME/LOCATION

Charlie's Tire

JOB NUMBER

PROBLEM: needs tires

REPAIRED: new tires

PARTS: 4-265-70-17

Goodyear

822.83

Charlie's Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0015

MAKE Ram

MODEL 17' 1500 4x4

SERIAL # JAM

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-2-2020

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: replaced bad inverte

REPAIRED: replaced inverte

PARTS: 1500w Inverte warranty Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0015

MAKE Ram

MODEL 17 1500

SERIAL # JEFF M.

OUR METER _____

MILES 85k mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-30-22

MECHANIC Tire Shop

JOB NAME/LOCATION Charles Tire

JOB NUMBER _____

PROBLEM: _____

REPAIRED: New tires

PARTS: LT265 70/17 Tego AT 1084, ⁵⁵ Charles Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0015</u> MAKE <u>Ram</u> MODEL <u>17' 1500</u> SERIAL # <u>Jett M.</u> HOUR METER _____ MILES <u>105K mi</u>		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>11-30-22</u> DATE COMPLETED _____ MECHANIC <u>All</u>	
PROBLEM: <u>Service & brake pads</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>replaced front & rear pads</u>					
PARTS: <u>F&R pads</u> <u>91.00</u> <u>Advance Auto Parts</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0015</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>RAM</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' 1500</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>8-17-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>
	JOB NUMBER _____

PROBLEM: weak battery

REPAIRED: replaced battery

PARTS: MTX94R 238.11 Interstate battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0015</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>1500 17'</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>JEFF M</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES <u>137k mi</u>			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>10-12-23</u> DATE COMPLETED <u>1-25-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER	
PROBLEM: <u>Exhaust leak</u>			
REPAIRED: <u>both ex manifold gaskets blown, drilled out broken bolts, replaced gaskets.</u>			
PARTS: <u>EX Parts</u>	<u>298.⁵⁹</u>	<u>Advance</u>	
<u>blades</u>	<u>15.90</u>	<u>NAPA</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0015</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Ram</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' 1500</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # <u>Jepp</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES <u>155K mi</u>		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>9-10-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop/Charles Tire</u> JOB NUMBER _____	
PROBLEM: <u>Service, new Tires</u>		
REPAIRED: <u>Service</u>		
PARTS: <u>4-265/70-17 P490 1120⁷⁷ Charles Tire</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0015</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Ram</u>		REASON		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' 1500</u>		PARTS	LABOR	COMPONENT LOCATION	
SERIAL # <u>Jeff M.</u>		OTHER _____		FRONT	REAR LEFT RIGHT UPPER LOWER
HOUR METER _____				OTHER _____	
MILES <u>163k mi</u>					

REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED	DATE: <u>3-11-25</u>	DATE COMPLETED: <u>3-11-25</u>
<input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH	MECHANIC: <u>Bryan</u>	
<input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____	JOB NAME/LOCATION	JOB NUMBER

PROBLEM: water pump

REPAIRED: replaced water pump, belt & Tensioner.

PARTS: pump kit, sensor & Tensioner 254.³⁷ Advance Auto
plugs 211.⁰⁷ O'Reilly Auto
belt & clamp 45.⁹⁹ O'Reilly Auto