

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0515</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>330C</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>12-13-19</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Bought used</u>				
REPAIRED: <u>serviced, repaired exhaust, removed stick</u>				
<u>bucket cylinder Repair</u> <u>Sealed Piston & Head</u> 856. ⁷⁶ <u>Thompson</u> <u>2 bushings</u> 33 P. <u>42</u> <u>Thompson</u>				
PARTS: <u>All Filters</u> 450. ⁶⁴ <u>Tenn Filter</u> <u>2-lower Hyd. comp. panels</u> 440. ⁰⁰ <u>White House Equipment</u> <u>Hour meter</u> <u>2-Pipes & clamp</u> 463. ⁷³ <u>Thompson</u> <u>4-batteries</u> 588. ⁸⁷ <u>Interstate Battery</u> <u>Flat Caps</u> 27 P. <u>Thompson</u> <u>Stick cylinder seals & Pack</u> 1,131. ⁸³ <u>Mid South hydraulics</u>				