

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                        |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                   |                                  |
|------------------------------------------------------------------------------|--|-------------------------|--|-----------------------------------|----------------------------------|
| EQUIP. # <u>201</u>                                                          |  | HOURS _____ DAYS _____  |  | BASIC MACHINE                     | HYDRAULIC ENGINE IMPLEMENTS      |
| MAKE <u>CAT</u>                                                              |  | REASON                  |  | POWER TRAIN                       | ELECTRIC DRIVE TRAIN UNEXPLAINED |
| MODEL <u>140H</u>                                                            |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                |                                  |
| SERIAL # <u>22K01863</u>                                                     |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER |                                  |
| HOUR METER _____                                                             |  |                         |  | OTHER _____                       |                                  |
| MILES _____                                                                  |  |                         |  |                                   |                                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                           |  |                         |  | DATE: <u>11-14-11</u>             | DATE COMPLETED <u>11-15-11</u>   |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                |  |                         |  | MECHANIC <u>JAMES</u>             |                                  |
| SMOKES SHORTED VIBRATE OTHER _____                                           |  |                         |  | JOB NAME/LOCATION<br><u>Shop</u>  | JOB NUMBER                       |
| PROBLEM: <u>service and check over</u>                                       |  |                         |  |                                   |                                  |
| REPAIRED: <u>washed + serviced replaced main front and rear wiper blades</u> |  |                         |  |                                   |                                  |
| PARTS: <u>2-18" wiper blades 28.50</u> <u>Advance Auto Parts</u>             |  |                         |  |                                   |                                  |
| <u>Eng oil Filter, Trans &amp; Hyd Filters 35.00</u> <u>Ken Filler Sales</u> |  |                         |  |                                   |                                  |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                              |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|--|----------------------------------------------|--|
| EQUIP. # <u>201</u>                                                                                                                       |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON                  |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>140H</u>                                                                                                                         |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                                                                                                          |  |                         |  | OTHER _____                                  |  |
| MILES _____                                                                                                                               |  |                         |  |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         |  | DATE: _____ DATE COMPLETED <u>8-29-12</u>    |  |
|                                                                                                                                           |  |                         |  | MECHANIC <u>James</u>                        |  |
|                                                                                                                                           |  |                         |  | JOB NAME/LOCATION <u>Franklin Ky</u>         |  |
|                                                                                                                                           |  |                         |  | JOB NUMBER _____                             |  |
| PROBLEM: <u>Left turntable lift cylinder cracked</u>                                                                                      |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
| REPAIRED: <u>removed cylinder, removed rod, welded barrel &amp; installed.</u>                                                            |  |                         |  |                                              |  |
| <u>lift cylinder functions stuck.</u>                                                                                                     |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
| PARTS: <u>N/A</u>                                                                                                                         |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |
|                                                                                                                                           |  |                         |  |                                              |  |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                                              |            |
|-----------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|------------------------------------------------------------------------------|------------|
| EQUIP. # <u>201</u>                                                                                                                           |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                                    |            |
| MAKE <u>CAT</u>                                                                                                                               |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                                 |            |
| MODEL <u>140H</u>                                                                                                                             |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                                           |            |
| SERIAL # _____                                                                                                                                |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                                            |            |
| HOUR METER _____                                                                                                                              |  |                         | OTHER _____                                                                  |            |
| MILES _____                                                                                                                                   |  |                         |                                                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____     |  |                         | DATE: <u>9-10-12</u> DATE COMPLETED <u>10-4-12</u><br>MECHANIC: <u>JAMES</u> |            |
|                                                                                                                                               |  |                         | JOB NAME/LOCATION<br><u>Franklin Ky</u>                                      | JOB NUMBER |
| PROBLEM: <u>left front tire flat</u>                                                                                                          |  |                         |                                                                              |            |
| REPAIRED: <u>replaced left front tire with new bias ply in stock.</u><br><u>ordered lean cylinder seal kit</u><br><u>packed lean cylinder</u> |  |                         |                                                                              |            |
| PARTS: <u>14.00X24 bias in stock</u> <u>oring in stock</u><br><u>lean cylinder packing 147.03</u> <u>Thompson</u>                             |  |                         |                                                                              |            |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                            |  | EQUIPMENT DOWNTIME     |             | COMPONENT CODES                           |                                  |
|------------------------------------------------------------------|--|------------------------|-------------|-------------------------------------------|----------------------------------|
| EQUIP. # <u>201</u>                                              |  | HOURS _____ DAYS _____ |             | BASIC MACHINE                             | HYDRAULIC ENGINE IMPLEMENTS      |
| MAKE <u>CAT</u>                                                  |  | REASON                 |             | POWER TRAIN                               | ELECTRIC DRIVE TRAIN UNEXPLAINED |
| MODEL <u>140H</u>                                                |  | PARTS _____            | LABOR _____ | COMPONENT LOCATION                        |                                  |
| SERIAL # _____                                                   |  | OTHER _____            |             | FRONT REAR LEFT RIGHT UPPER LOWER         |                                  |
| HOUR METER _____                                                 |  |                        |             | OTHER _____                               |                                  |
| MILES _____                                                      |  |                        |             |                                           |                                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED               |  |                        |             | DATE: _____ DATE COMPLETED <u>12-6-12</u> |                                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                    |  |                        |             | MECHANIC <u>JAMES</u>                     |                                  |
| SMOKES SHORTED VIBRATE OTHER _____                               |  |                        |             | JOB NAME/LOCATION                         | JOB NUMBER                       |
|                                                                  |  |                        |             | <u>Shop</u>                               |                                  |
| PROBLEM: <u>Turntable lift cylinder trunnions Freezing up.</u>   |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
| REPAIRED: <u>Removed left trunnion cleaned up and Assembled.</u> |  |                        |             |                                           |                                  |
| <u>Removed right trunnion cleaned up and Assembled.</u>          |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
| PARTS: <u>NO PARTS</u>                                           |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |
|                                                                  |  |                        |             |                                           |                                  |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                               |                         | EQUIPMENT DOWNTIME                           |  | COMPONENT CODES               |  |
|-----------------------------------------------------|-------------------------|----------------------------------------------|--|-------------------------------|--|
| EQUIP. # <u>201</u>                                 | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |                               |  |
| MAKE <u>CAT</u>                                     | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |                               |  |
| MODEL <u>140H</u>                                   | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |  |                               |  |
| SERIAL # _____                                      | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |  |                               |  |
| HOUR METER _____                                    |                         | OTHER _____                                  |  |                               |  |
| MILES _____                                         |                         |                                              |  |                               |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  |                         | DATE: _____                                  |  | DATE COMPLETED <u>4-16-13</u> |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH       |                         | MECHANIC <u>JAMES</u>                        |  |                               |  |
| SMOKES SHORTED VIBRATE OTHER _____                  |                         | JOB NAME/LOCATION <u>Shop</u>                |  | JOB NUMBER _____              |  |
| PROBLEM: <u>left steer cylinder leaking</u>         |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
| REPAIRED: <u>packed left steering cylinder</u>      |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
| PARTS: <u>Seal Kit</u> <u>67.83</u> <u>Thompson</u> |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |
|                                                     |                         |                                              |  |                               |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                             |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|-------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>201</u>                                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>CAT</u>                                                   |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>140H</u>                                                 |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                                    |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                                  |  |                         | OTHER _____                                  |                  |
| MILES _____                                                       |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                |  |                         | DATE: _____ DATE COMPLETED <u>8-12-13</u>    |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                     |  |                         | MECHANIC <u>Gary &amp; Tricky</u>            |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                |  |                         | JOB NAME/LOCATION <u>Shop</u>                | JOB NUMBER _____ |
| PROBLEM: <u>cutting edge worn out</u>                             |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
| REPAIRED: <u>replaced cutting edge.</u>                           |  |                         |                                              |                  |
| <u>rotated end bits</u>                                           |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
| PARTS: <u>edges &amp; hardware \$323.15 white House equipment</u> |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |
|                                                                   |  |                         |                                              |                  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |                        | EQUIPMENT DOWNTIME                                       | COMPONENT CODES                                                                                                      |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--|
| EQUIP. # <u>201</u>                                                                                                                       | HOURS _____ DAYS _____ | REASON<br><br>PARTS _____ LABOR _____<br><br>OTHER _____ | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                                                                            |  |
| MAKE <u>CAT</u>                                                                                                                           |                        |                                                          | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                                                                         |  |
| MODEL <u>140H</u>                                                                                                                         |                        |                                                          | COMPONENT LOCATION<br><br>FRONT REAR LEFT RIGHT UPPER LOWER                                                          |  |
| SERIAL # _____                                                                                                                            | HOUR METER _____       |                                                          | OTHER _____                                                                                                          |  |
| MILES _____                                                                                                                               |                        |                                                          |                                                                                                                      |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |                        |                                                          | DATE: _____ DATE COMPLETED <u>8-21-13</u><br>MECHANIC <u>James</u><br>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____ |  |
| PROBLEM: <u>left blade slide hose blown</u>                                                                                               |                        |                                                          |                                                                                                                      |  |
| REPAIRED: <u>replaced hose and guard hardware</u>                                                                                         |                        |                                                          |                                                                                                                      |  |
| PARTS: <u>hose assembly</u> <u>176.29</u> <u>NAPA</u><br><u>Hardware</u> <u>30.00</u> <u>TJC</u>                                          |                        |                                                          |                                                                                                                      |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|---------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>201</u>                                           |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>CAT</u>                                               |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>140H</u>                                             |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                                |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                              |  |                         | OTHER _____                                  |            |
| MILES _____                                                   |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED            |  |                         | DATE: _____ DATE COMPLETED <u>4-25-14</u>    |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                 |  |                         | MECHANIC <u>JAMES</u>                        |            |
| SMOKES SHORTED VIBRATE OTHER _____                            |  |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |
| PROBLEM: <u>cow broke step rubbers on both sides.</u>         |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
| REPAIRED: <u>cut out new step rubbers used conveyor belt.</u> |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
| PARTS: <u>Free belt from Vulcan</u>                           |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |

EQUIPMENT  
REPAIRS

DATE 11-5-14

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #201 Cab 140H Grader

REPAIRS MADE changed engine oil & filter  
Transmission filter, & fuel filter

HOURS WORKED \_\_\_\_\_

PARTS USED

Filters

Two filter sets

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|----------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>201</u>                                |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Cat</u>                                    |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>140H</u>                                  |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                  |            |
| MILES _____                                        |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: _____ DATE COMPLETED <u>8-12-15</u>    |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>JAMES + Steven</u>               |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |
| PROBLEM: <u>check over</u>                         |  |                         |                                              |            |
| REPAIRED: <u>replaced air filters</u>              |  |                         |                                              |            |
| <u>tapped off A/C</u>                              |  |                         |                                              |            |
| <u>replaced clean air pipe</u>                     |  |                         |                                              |            |
| PARTS: <u>Air Filters 104.04 Thompson</u>          |  |                         |                                              |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                               |                                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|--------------|-----------------|-----------------|--------------|-----------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>201</u><br>MAKE <u>Cat</u><br>MODEL <u>140H</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____                                                                                                                                                                                                                                          | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____                                                                            |                                  |              |                 |                 |              |                 |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                                                                                                                                                                                                                                                 |                                                                                                               | DATE: _____ DATE COMPLETED <u>2-18-16</u><br>MECHANIC <u>JAMES &amp; BRIAN</u><br><table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">JOB NAME/LOCATION<br/><u>Shop</u></td> <td style="width: 50%;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>Shop</u> | JOB NUMBER   |                 |                 |              |                 |
| JOB NAME/LOCATION<br><u>Shop</u>                                                                                                                                                                                                                                                                                                                                                          | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |
| PROBLEM: <u>Muffler burned out</u><br><br><br>                                                                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |
| REPAIRED: <u>replaced muffler and stack pipe cut hood out for muffler modification</u><br><br><br><br><br><br>                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |
| <table style="width: 100%;"> <tr> <td style="width: 40%;">PARTS: <u>muffler + stack</u></td> <td style="width: 20%; text-align: right;"><u>86.76</u></td> <td style="width: 40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Coupling</u></td> <td style="text-align: right;"><u>90.56</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> </table><br><br> |                                                                                                               |                                                                                                                                                                                                                                                                                 | PARTS: <u>muffler + stack</u>    | <u>86.76</u> | <u>Thompson</u> | <u>Coupling</u> | <u>90.56</u> | <u>Thompson</u> |
| PARTS: <u>muffler + stack</u>                                                                                                                                                                                                                                                                                                                                                             | <u>86.76</u>                                                                                                  | <u>Thompson</u>                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |
| <u>Coupling</u>                                                                                                                                                                                                                                                                                                                                                                           | <u>90.56</u>                                                                                                  | <u>Thompson</u>                                                                                                                                                                                                                                                                 |                                  |              |                 |                 |              |                 |

**TEC**  
THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

|                                                                                                                                                     |                                                                                                               |                                                                                                                                                                                                               |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>EQUIPMENT INFORMATION</b><br># = <u>201</u><br>TYPE <u>CAT</u><br>MODEL <u>140 G</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____        | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____<br>_____ |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____           |                                                                                                               | DATE: _____ DATE COMPLETED <u>7-6-16</u><br>MECHANIC <u>Charles + Steve B</u><br>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____                                                                               |
| PROBLEM: _____<br>_____<br>_____                                                                                                                    |                                                                                                               |                                                                                                                                                                                                               |
| REPAIRED: _____<br><u>6 TIRES NEW</u><br><u>SERVICED</u><br><u>blade brass</u><br><u>support plate for blade bracket</u><br>_____<br>_____<br>_____ |                                                                                                               |                                                                                                                                                                                                               |

Brass strip  
other brass

55.29  
in stock

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                                                                    |                                                                                              | EQUIPMENT DOWNTIME                                                                                                                                                                                                   | COMPONENT CODES |  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|--|
| EQUIP # <u>201</u>                                                                                                                                                                       | HOURS _____ DAYS _____<br><br>REASON _____<br><br>PARTS _____ LABOR _____<br><br>OTHER _____ | BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS<br><br>POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED<br><br>COMPONENT LOCATION<br><br>FRONT    REAR    LEFT    RIGHT    UPPER    LOWER<br><br>OTHER _____ |                 |  |
| MAKE <u>CAT</u>                                                                                                                                                                          |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| MODEL <u>140H</u>                                                                                                                                                                        |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| SERIAL # _____                                                                                                                                                                           |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| HOUR METER _____                                                                                                                                                                         |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| MILES _____                                                                                                                                                                              |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED<br><br>OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH<br><br>SMOKES    SHORTED    VIBRATE    OTHER _____ |                                                                                              | DATE: _____ DATE COMPLETED <u>10-10-16</u><br><br>MECHANIC <u>Charles</u><br><br>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____                                                                                      |                 |  |
| PROBLEM: <u>RT steer cylinder leaking</u><br><u>RT Oscillating cylinder leaking</u>                                                                                                      |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| REPAIRED: <u>Re sealed both cylinders</u>                                                                                                                                                |                                                                                              |                                                                                                                                                                                                                      |                 |  |
| <u>2 - seal Kits    \$161.23    Thompson Machinery</u>                                                                                                                                   |                                                                                              |                                                                                                                                                                                                                      |                 |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                       |                          |                         |             |                      |                         |             |                 |                          |                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------|-------------|----------------------|-------------------------|-------------|-----------------|--------------------------|-----------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>201</u><br>MAKE <u>CAT</u><br>MODEL <u>140H</u><br>SERIAL # <u>Grader</u><br>HOUR METER _____<br>MILES <u>New HR</u>                                                                                                                                                                                                                                                                                                                                                                                           | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS<br>POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT    REAR    LEFT    RIGHT    UPPER    LOWER<br>OTHER _____ |                          |                         |             |                      |                         |             |                 |                          |                 |
| REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED<br>OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH<br>SMOKES    SHORTED    VIBRATE    OTHER _____                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                               | DATE: _____ DATE COMPLETED _____<br>MECHANIC <u>JAMES + Steven B</u><br>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____                                                                                                                |                          |                         |             |                      |                         |             |                 |                          |                 |
| PROBLEM: <u>Service, check over, HR meter</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                                                                               |                                                                                                                                                                                                                                       |                          |                         |             |                      |                         |             |                 |                          |                 |
| REPAIRED: <u>serviced, new HR meter</u><br><u>Decal update</u><br><u>needs slide guide build up.</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                                                                               |                                                                                                                                                                                                                                       |                          |                         |             |                      |                         |             |                 |                          |                 |
| <table style="width: 100%;"> <tr> <td style="width: 40%;">PARTS: <u>Air Filter</u></td> <td style="width: 20%; text-align: center;"><u>39.<sup>03</sup></u></td> <td style="width: 40%; text-align: center;"><u>Napa</u></td> </tr> <tr> <td><u>Other filters</u></td> <td style="text-align: center;"><u>62.<sup>29</sup></u></td> <td style="text-align: center;"><u>Napa</u></td> </tr> <tr> <td><u>HR meter</u></td> <td style="text-align: center;"><u>105.<sup>39</sup></u></td> <td style="text-align: center;"><u>Thompson</u></td> </tr> </table> |                                                                                                               |                                                                                                                                                                                                                                       | PARTS: <u>Air Filter</u> | <u>39.<sup>03</sup></u> | <u>Napa</u> | <u>Other filters</u> | <u>62.<sup>29</sup></u> | <u>Napa</u> | <u>HR meter</u> | <u>105.<sup>39</sup></u> | <u>Thompson</u> |
| PARTS: <u>Air Filter</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <u>39.<sup>03</sup></u>                                                                                       | <u>Napa</u>                                                                                                                                                                                                                           |                          |                         |             |                      |                         |             |                 |                          |                 |
| <u>Other filters</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <u>62.<sup>29</sup></u>                                                                                       | <u>Napa</u>                                                                                                                                                                                                                           |                          |                         |             |                      |                         |             |                 |                          |                 |
| <u>HR meter</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | <u>105.<sup>39</sup></u>                                                                                      | <u>Thompson</u>                                                                                                                                                                                                                       |                          |                         |             |                      |                         |             |                 |                          |                 |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

|                                                                |  |                         |  |                                              |  |
|----------------------------------------------------------------|--|-------------------------|--|----------------------------------------------|--|
| EQUIPMENT INFORMATION                                          |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                              |  |
| EQUIP. # <u>1301</u>                                           |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                |  | REASON                  |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>140H</u>                                              |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                 |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER <u>225 HRS</u>                                      |  |                         |  | OTHER _____                                  |  |
| MILES _____                                                    |  |                         |  |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED             |  |                         |  | DATE: _____ DATE COMPLETED <u>8-30-18</u>    |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                  |  |                         |  | MECHANIC <u>James</u>                        |  |
| SMOKES SHORTED VIBRATE OTHER _____                             |  |                         |  | JOB NAME/LOCATION <u>Shops</u>               |  |
|                                                                |  |                         |  | JOB NUMBER _____                             |  |
| PROBLEM: _____                                                 |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| REPAIRED: <u>serviced and adjusted Turntable</u>               |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| PARTS: <u>screen &amp; magnet</u> <u>58.00</u> <u>Thompson</u> |  |                         |  |                                              |  |
| <u>oil Filter</u> <u>9.40</u> <u>NAPA</u>                      |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |
| _____                                                          |  |                         |  |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                             |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                       |                  |
|-------------------------------------------------------------------|--|-------------------------|-------------------------------------------------------|------------------|
| EQUIP. # <u>1301</u>                                              |  | HOURS _____ DAYS _____  | BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS    |                  |
| MAKE <u>CAT</u>                                                   |  | REASON _____            | POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED |                  |
| MODEL <u>140H</u>                                                 |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                    |                  |
| SERIAL # _____                                                    |  | OTHER _____             | FRONT    REAR    LEFT    RIGHT    UPPER    LOWER      |                  |
| HOUR METER _____                                                  |  |                         | OTHER _____                                           |                  |
| MILES _____                                                       |  |                         |                                                       |                  |
| REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED |  |                         | DATE: _____ DATE COMPLETED <u>7-12-18</u>             |                  |
| OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH      |  |                         | MECHANIC <u>Charles</u>                               |                  |
| SMOKES    SHORTED    VIBRATE    OTHER _____                       |  |                         | JOB NAME/LOCATION <u>Shop</u>                         | JOB NUMBER _____ |
| PROBLEM: <u>bad battery</u>                                       |  |                         |                                                       |                  |
| <u>Hard to push clutch</u>                                        |  |                         |                                                       |                  |
| REPAIRED: <u>replace batteries</u>                                |  |                         |                                                       |                  |
| <u>replaced clutch cable</u>                                      |  |                         |                                                       |                  |
| PARTS: <u>2-31P-MHD</u> <u>281.00</u> <u>IBS</u>                  |  |                         |                                                       |                  |
| <u>Cable + Springs</u> <u>216.71</u> <u>Thompson</u>              |  |                         |                                                       |                  |
| <u>seals</u> <u>4.40</u> <u>Thompson</u>                          |  |                         |                                                       |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                   |  |                                                                                                               |  |                                                                                                                                                                                                      |  |
|---------------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1301</u><br>MAKE <u>Cat</u><br>MODEL <u>140H</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____ |  | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ |  | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____ |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____         |  |                                                                                                               |  | DATE <u>10-23-18</u> DATE COMPLETED <u>10-23-18</u><br>MECHANIC <u>James</u><br>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____                                                                       |  |
| PROBLEM: <u>starter</u>                                                                                                                           |  |                                                                                                               |  |                                                                                                                                                                                                      |  |
| REPAIRED: <u>replaced solenoid + rebuilt starter</u>                                                                                              |  |                                                                                                               |  |                                                                                                                                                                                                      |  |
| PARTS: <u>solenoid</u> <u>63.57</u> <u>Crooks' Auto Electric</u><br><u>starter repair</u> <u>194.41</u><br><u>257.84</u>                          |  |                                                                                                               |  |                                                                                                                                                                                                      |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|-------------------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1301</u>                                                          |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>Cat</u>                                                               |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>140H</u>                                                             |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # <u>Motor Grader</u>                                                  |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                                              |  |                         | OTHER _____                                  |                  |
| MILES _____                                                                   |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                            |  |                         | DATE: <u>6-8-20</u> DATE COMPLETED _____     |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                 |  |                         | MECHANIC <u>Charles</u>                      |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                            |  |                         | JOB NAME/LOCATION <u>James Brummett</u>      | JOB NUMBER _____ |
| PROBLEM: <u>Add scarifiers</u>                                                |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
| REPAIRED: <u>pins and Grommets for scarifier</u>                              |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
| PARTS: <u>7 pins &amp; Grommets</u> <u>1/4" <sup>RG</sup></u> <u>Thompson</u> |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |
|                                                                               |  |                         |                                              |                  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

|                                                                                                                                                                                                                        |                                                                                                               |                                                                                                                                                                                                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1301</u><br>MAKE <u>CAT</u><br>MODEL <u>140H</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____                                                                      | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____ |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                                                                              |                                                                                                               | DATE: <u>11-18-20</u> DATE COMPLETED <u>12-1-20</u><br>MECHANIC <u>Ben</u><br>JOB NAME/LOCATION <u>V. Tan Farm</u> JOB NUMBER _____                                                                  |
| PROBLEM: <u>Transmission checks</u><br><u>not going into forward gears</u>                                                                                                                                             |                                                                                                               |                                                                                                                                                                                                      |
| REPAIRED: <u>changed Transmission filter &amp; suction screen.</u><br><u>changed four bad valve body solenoids</u><br><u>serviced</u>                                                                                  |                                                                                                               |                                                                                                                                                                                                      |
| PARTS: <u>Filter screen &amp; orings 66.45 Thompson</u><br><u>2 solenoids 341.00 Thompson</u><br><u>2 solenoids &amp; filters 535.77 Thompson</u><br><u>2 cabin filters 64.79 Napa</u><br><u>Filter 48.61 Thompson</u> |                                                                                                               |                                                                                                                                                                                                      |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME                                 | COMPONENT CODES                              |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|----------------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1301</u>                                                                                                                      |  | HOURS _____ DAYS _____                             | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>Cat</u>                                                                                                                           |  | REASON _____                                       | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>140H</u>                                                                                                                         |  | PARTS _____ LABOR _____                            | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____                                        | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                                                                                                          |  |                                                    | OTHER _____                                  |  |
| MILES _____                                                                                                                               |  |                                                    |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  | DATE: _____ DATE COMPLETED <u>8-18-21</u>          |                                              |  |
|                                                                                                                                           |  | MECHANIC <u>Ben</u>                                |                                              |  |
| PROBLEM: <u>blown hose at circle motor</u>                                                                                                |  | JOB NAME/LOCATION <u>Eastgate</u> JOB NUMBER _____ |                                              |  |
| REPAIRED: <u>replaced hose</u>                                                                                                            |  |                                                    |                                              |  |
| PARTS: <u>hose</u> <u>163.14</u> <u>Crook Auto</u>                                                                                        |  |                                                    |                                              |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME                                                                                                         | COMPONENT CODES                              |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|----------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1301</u>                                                                                                                      |  | HOURS _____ DAYS _____                                                                                                     | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____                                                                                                               | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>140H</u>                                                                                                                         |  | PARTS _____ LABOR _____                                                                                                    | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____                                                                                                                | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                                                                                                          |  |                                                                                                                            | OTHER _____                                  |  |
| MILES _____                                                                                                                               |  |                                                                                                                            |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  | DATE: _____ DATE COMPLETED <u>11-18-22</u><br>MECHANIC <u>Ben</u><br>JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____ |                                              |  |
| PROBLEM: <u>dead batteries</u>                                                                                                            |  |                                                                                                                            |                                              |  |
| REPAIRED: <u>replaced batteries</u>                                                                                                       |  |                                                                                                                            |                                              |  |
| PARTS: <u>2-GRP 31</u> <u>307 31</u> <u>Advance Auto Parts</u>                                                                            |  |                                                                                                                            |                                              |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                  |                               | EQUIPMENT DOWNTIME                                 | COMPONENT CODES  |  |
|--------------------------------------------------------|-------------------------------|----------------------------------------------------|------------------|--|
| EQUIP. # <u>1301</u>                                   | HOURS _____ DAYS _____        | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS          |                  |  |
| MAKE <u>CAT</u>                                        | REASON _____                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED       |                  |  |
| MODEL <u>140H</u>                                      | PARTS _____ LABOR _____       | COMPONENT LOCATION                                 |                  |  |
| SERIAL # _____                                         | OTHER _____                   | FRONT REAR LEFT RIGHT UPPER LOWER                  |                  |  |
| HOUR METER _____                                       |                               | OTHER _____                                        |                  |  |
| MILES _____                                            |                               |                                                    |                  |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED     |                               | DATE <u>10-17-23</u> DATE COMPLETED <u>11-9-23</u> |                  |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH          |                               | MECHANIC <u>ALL</u>                                |                  |  |
| SMOKES SHORTED VIBRATE OTHER _____                     |                               | JOB NAME/LOCATION<br><u>Shop</u>                   | JOB NUMBER _____ |  |
| PROBLEM: <u>leaks &amp; console problems</u>           |                               |                                                    |                  |  |
| REPAIRED: <u>Per Made guard For Trans.</u>             |                               |                                                    |                  |  |
| <u>packed seatine cylinder &amp; CAT Air. cylinder</u> |                               |                                                    |                  |  |
| <u>replaced console base, both air hoses going to</u>  |                               |                                                    |                  |  |
| <u>gauges.</u>                                         |                               |                                                    |                  |  |
| PARTS: <u>cylinder</u>                                 | <u>119.16</u>                 | <u>Thompson</u>                                    |                  |  |
| <u>Seal Kits</u>                                       | <u>\$ 118.31 &amp; 129.54</u> | <u>Thompson</u>                                    |                  |  |
| <u>bearings</u>                                        | <u>\$ 2.00</u>                | <u>Thompson</u>                                    |                  |  |
| <u>base</u>                                            | <u>535.00</u>                 | <u>Thompson</u>                                    |                  |  |
| <u>2 hoses</u>                                         | <u>\$ 3.22</u>                | <u>Thompson</u>                                    |                  |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION |                         | EQUIPMENT DOWNTIME                           | COMPONENT CODES |  |
|-----------------------|-------------------------|----------------------------------------------|-----------------|--|
| EQUIP. # <u>1301</u>  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                 |  |
| MAKE <u>Cat</u>       | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                 |  |
| MODEL <u>140H</u>     | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                 |  |
| SERIAL # _____        | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                 |  |
| HOUR METER _____      |                         | OTHER _____                                  |                 |  |
| MILES _____           |                         |                                              |                 |  |

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 5-6-25

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: blown hose.

REPAIRED: replaced transmission hose and hyd hose that was leaking.

PARTS: 2 Hoses. 262.16 Nashville Rubber & Gasket.

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION |                         | EQUIPMENT DOWNTIME                           | COMPONENT CODES |  |
|-----------------------|-------------------------|----------------------------------------------|-----------------|--|
| EQUIP. # <u>1301</u>  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                 |  |
| MAKE <u>CAT</u>       | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                 |  |
| MODEL <u>140H</u>     | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                 |  |
| SERIAL # _____        | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                 |  |
| HOUR METER _____      |                         | OTHER _____                                  |                 |  |
| MILES _____           |                         |                                              |                 |  |

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE 5-8-25 DATE COMPLETED \_\_\_\_\_  
 MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: hose leaking and one with pin hole.

REPAIRED: replaced one coolant hose and one Trans hose

PARTS: hoses 262.79 Crack's Electric