

Capital Volvo Truck and Trailer - Montgomery (Volvo)

185 West Blvd Montgomery, Alabama 36108
Phone: (334) 262-8856 - Fax: (334) 262-8081

ASIST

Case Number: 18974711
Repair Order Number: 5463
Purchase Order Number: NEED
Service Advisor: BECK, BEN - Case Date 2024-11-18 12:55:20 -0600
ETR: 3/20/2025 at 02:24 pm CDT

Customer: Youngs Trucking**Unit Number:** 120

Address: 1197 MCCAIN ROAD WETUMPKA,
AL 36092

Phone: (334) 303-6793**Fax:** N/A**Customer Number:** 00001**Asset:** 2011 Volvo VNL**Serial Number:** BN532202**VIN:** 4V4NC9EJ0BN532202**Engine:** D13**Engine Hours:** 7590**Odometer:** 1394880 Miles**Warranty Start:** 12/10/2010 12:00:00**In Service:** 14 Years 3 Months

BN532202

1 CHECK AND ADVISE WATER LEAK**Complaint:** CHECK AND ADVISE WATER LEAK

Cause: Unit is not warranty due to fuel getting into coolant from injector sleeves (you said not to quote the injectors/sleeves). Also, fan clutch is locked up on unit which caused it to run hot.

		Quantity	Price	Totals
Labor:				\$2,520.00
Parts:	EXPANSION TANK	1.0		
	THERMOSTAT	1.0		
	SEALING RING	1.0		
	SEALING STRIP	1.0		
	CONNECTION PIPE	1.0		
	GASKET	3.0		
	O-RING	1.0		
	SEAL RING	2.0		
	FLANGE SCREW	1.0		
	O-RING	1.0		
	SEAL RING	1.0		
	GASKET	3.0		
	FAN HUB	1.0		
	hose clamp (21078879)	4.0		
	INSTALLATION KIT	1.0		
	GASKET	6.0		
	GASKET	1.0		
	V-BAND CLAMP	1.0		
	CYL BLOCK COVER	1.0		
	SENSOR	1.0		
	Parts Total			\$2,697.20
Operation Total:				\$5,217.20

ASSET

Capital Volvo Truck and Trailer - Montgomery (Volvo)**Customer:** Youngs Trucking**Unit Number:** 120**Case Number:** 18974711**Asset:** 2011 Volvo VNL**VIN:** 4V4NC9EJ0BN532202

BN532202

2 Check 22 Inspection

	Quantity	Price	Totals
Labor:			\$540.00
Parts: AIR DEFLECTOR	1.0		
Operation Total:			\$873.87

	Parts	\$3,031.07
	Labor	\$3,060.00
	Shop Supplies	\$200.00
	Freight	\$50.00
	Taxes	\$303.11
	Total	\$6,644.18

4/15/25

we paid 940.50 for
 this assessment at Cap
 Volvo. Truck needs 6644
 worth of work. Edmund
 basically gave truck up
 We rep'd from Cap Volvo
 we will post on FB "AS IS"

ASIST

Capital Volvo Truck and Trailer - Montgomery (Volvo)**Customer:** Youngs Trucking**Unit Number:** 120**Case Number:** 18974711**Asset:** 2011 Volvo VNL**VIN:** 4V4NC9EJ0BN532202

BN532202

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED BY: _____ DATE: ____/____/____

ESTIMATE