



TRACTOR & EQUIPMENT COMPANY

3305 HWY 77 PANAMA CITY, FL. 32405

To Whom It May Concern,

This letter is to document the monitor replacement on Komatsu PC210LC-10, serial number 450299.

On February 12, 2025, the machine's monitor was replaced due to a CAN termination failure. At the time of replacement, the original machine hours were 6,932. The replacement monitor installed was a used unit with 18,154 hours.

In accordance with federal regulations, machine hours cannot be reduced. Therefore, the hour meter was updated to reflect the higher reading from the replacement monitor.

If there are any questions or concerns regarding this matter, please feel free to contact me directly.

Sincerely,
Adam Sheppard
Service Manager
Tractor & Equipment Company
asheppard@tec1943.com