



**MON-10 FAILURE CODE [DV00KB] (ALARM BUZZER: SHORT CIRCUIT (KB))**

- ★ Nature of failure: A short circuit with the power source has occurred in the output circuit of the alarm buzzer
- ★ Before starting troubleshooting, check that fuse BT2-2 is normal (if the fuse is blown, there has probably been a surge of current caused by a short circuit, so check the related circuits).

**MON-10 Related electrical circuit diagram**

BJH10603

EQUIPMENT  
REPAIRS

DATE 11-7-08

MILEAGE/HOURS 3321 HRS

EQUIPMENT REPAIRED #1006 HM300-1 #1158

REPAIRS MADE Picked up at Richie Bros

---

---

HOURS WORKED \_\_\_\_\_

PARTS USED

Truck 90,000 Auction

## EQUIPMENT REPAIRS

DATE 11-10-08

MILEAGE/HOURS 3321 HRS

EQUIPMENT REPAIRED #1006 HM300-1 1158

REPAIRS MADE replaced both batteries

HOURS WORKED \_\_\_\_\_

## PARTS USED

2-4D 305.79 Interstate

EQUIPMENT  
REPAIRS

DATE 11-17-08

MILEAGE/HOURS 3321 HRS

EQUIPMENT REPAIRED #1006 HM300-1 #1158

REPAIRS MADE changed all oils and Filters, both  
wiper blades, seal & boot at hitch replaced  
most grease fittings Decals & numbers  
Replaced RT mirror checked wheel bolts

HOURS WORKED \_\_\_\_\_

PARTS USED

|                |                    |                 |
|----------------|--------------------|-----------------|
| Filters + Seal | 697. <sup>00</sup> | Power Equipment |
| Filters        | 91. <sup>00</sup>  | Tenn Filter     |

|                       |                   |      |
|-----------------------|-------------------|------|
| Lamps, bulbs & screws | 66. <sup>00</sup> | NAPA |
| Wiper blade, rear     | 15. <sup>00</sup> | NAPA |
| " " front             | In stock          |      |

|                 |                   |      |
|-----------------|-------------------|------|
| grease fittings | 15. <sup>00</sup> | LDC  |
| grease fittings | 22. <sup>00</sup> | NAPA |

|           |                      |                      |
|-----------|----------------------|----------------------|
| RT mirror | \$229. <sup>00</sup> | White Wave Equipment |
|-----------|----------------------|----------------------|

EQUIPMENT  
REPAIRS

DATE 1-21-09

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #1006 H4M300 Komatsu

REPAIRS MADE RAN over with DFR

Took out 1 battery & battery box.

Fix battery box at late-date.

HOURS WORKED \_\_\_\_\_

PARTS USED

1-40 Battery \$152.90 Interstate

EQUIPMENT  
REPAIRS

DATE \_\_\_\_\_

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED \_\_\_\_\_

REPAIRS MADE \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


HOURS WORKED \_\_\_\_\_

PARTS USED



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                                                                                                                                                      |      | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------------------------|----------------------------------------------|------------|-------|------|-----------------|-------|-------|------|------|-------|--|--|--|-------|--|--|--|---------------------|
| EQUIP. # <u>1006</u>                                                                                                                                                                                                                                                       |      | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| MAKE <u>Komatsu</u>                                                                                                                                                                                                                                                        |      | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| MODEL <u>Hm300-1</u>                                                                                                                                                                                                                                                       |      | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| SERIAL # _____                                                                                                                                                                                                                                                             |      | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| HOUR METER _____                                                                                                                                                                                                                                                           |      |                         | OTHER _____                                  |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| MILES _____                                                                                                                                                                                                                                                                |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| REASON FOR FAILURE: <u>BROKEN</u> WORN ABUSE LOOSE SEIZED                                                                                                                                                                                                                  |      |                         | DATE: _____ DATE COMPLETED <u>3-18-09</u>    |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                                                                                                                                                                                                              |      |                         | MECHANIC <u>James</u>                        |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| SMOKES SHORTED VIBRATE OTHER _____                                                                                                                                                                                                                                         |      |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| PROBLEM: <u>wrecked</u>                                                                                                                                                                                                                                                    |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| REPAIRED: <u>removed battery box assembly</u><br><u>straightened battery box best as I could not</u><br><u>perfect. Made new lid. Painted</u><br><u>re-used all old parts</u>                                                                                              |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <table><tr><td>paint</td><td>9.41</td><td>Power Equipment</td><td>16.41</td></tr><tr><td>bolts</td><td>7.00</td><td>NAPA</td><td>61.62</td></tr><tr><td></td><td></td><td></td><td>57.07</td></tr><tr><td></td><td></td><td></td><td><u>135.10</u> Total</td></tr></table> |      |                         |                                              |            | paint | 9.41 | Power Equipment | 16.41 | bolts | 7.00 | NAPA | 61.62 |  |  |  | 57.07 |  |  |  | <u>135.10</u> Total |
| paint                                                                                                                                                                                                                                                                      | 9.41 | Power Equipment         | 16.41                                        |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| bolts                                                                                                                                                                                                                                                                      | 7.00 | NAPA                    | 61.62                                        |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
|                                                                                                                                                                                                                                                                            |      |                         | 57.07                                        |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
|                                                                                                                                                                                                                                                                            |      |                         | <u>135.10</u> Total                          |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| PARTS: <u>stack, discs</u> <u>31.15</u> <u>Tractor Supply</u>                                                                                                                                                                                                              |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <u>fuel &amp; stack</u> <u>30.41</u> <u>"</u>                                                                                                                                                                                                                              |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <u>paint &amp; putty</u> <u>13.73</u> <u>NAPA</u>                                                                                                                                                                                                                          |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <u>2-prime</u> <u>11.75</u> <u>NAPA</u>                                                                                                                                                                                                                                    |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <u>3-prime</u> <u>17.20</u> <u>Advance</u>                                                                                                                                                                                                                                 |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |
| <u>3-prime</u> <u>14.36</u> <u>Tractor supply</u>                                                                                                                                                                                                                          |      |                         |                                              |            |       |      |                 |       |       |      |      |       |  |  |  |       |  |  |  |                     |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|---------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1006</u>                                          |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                           |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>Hm300</u>                                            |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # <u>1158</u>                                          |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                              |  |                         | OTHER _____                                  |            |
| MILES _____                                                   |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED            |  |                         | DATE: _____ DATE COMPLETED <u>P-26-09</u>    |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                 |  |                         | MECHANIC <u>JAMES</u>                        |            |
| SMOKES SHORTED VIBRATE OTHER _____                            |  |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |
| PROBLEM: <u>won't start</u>                                   |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
| REPAIRED: <u>replaced one bad battery other battery good.</u> |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
| PARTS: <u>1-4D Battery \$152.90 Interstate battery</u>        |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |
|                                                               |  |                         |                                              |            |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|---------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1006</u>                                          |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                           |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>HM300-1</u>                                          |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                                |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                              |  |                         | OTHER _____                                  |            |
| MILES _____                                                   |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED            |  |                         | DATE: _____ DATE COMPLETED <u>9-22-10</u>    |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                 |  |                         | MECHANIC <u>JAMES</u>                        |            |
| SMOKES SHORTED VIBRATE OTHER _____                            |  |                         | JOB NAME/LOCATION<br><u>Hearthside</u>       | JOB NUMBER |
| PROBLEM: <u>Fuel line leak - TANK hose</u>                    |  |                         |                                              |            |
| REPAIRED: <u>Replaced fuel line from tank to engine block</u> |  |                         |                                              |            |
| PARTS: <u>hose as. 171.75 Nashville Rubber &amp; Gasket</u>   |  |                         |                                              |            |

EQUIPMENT  
REPAIRS

DATE 9-23-10

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #1006

REPAIRS MADE Installed load counter

\_\_\_\_\_

\_\_\_\_\_

HOURS WORKED \_\_\_\_\_

PARTS USED

Tally Counter \$17.<sup>00</sup> White House Equipment

EQUIPMENT  
REPAIRS

DATE 11-8-11

MILEAGE/HOURS 4K HRS

EQUIPMENT REPAIRED #1006 Komatsu HM300-1 (1158)

REPAIRS MADE Serviced

Disconnected driver side power window, actuator  
in door is bad. Washed

HOURS WORKED \_\_\_\_\_

PARTS USED

Oil Filter 36.39  
Fuel Filters 20.66  
Air Filter Outer 35.50  
57.74

150.29  
+ TAX 15.00

165.29

Tenn Filter

Fuel & Trans Filters  
Coolant Filter  
Trans. & steer filters

32.98  
16.00

Tenn Filter  
NAPA  
White Horse Equipment



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                              |                         | EQUIPMENT DOWNTIME                           | COMPONENT CODES  |  |
|----------------------------------------------------|-------------------------|----------------------------------------------|------------------|--|
| EQUIP. # <u>1006</u>                               | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |  |
| MAKE <u>Komatsu</u>                                | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |  |
| MODEL <u>Nm300-1</u>                               | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |  |
| SERIAL # _____                                     | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |  |
| HOUR METER _____                                   |                         | OTHER _____                                  |                  |  |
| MILES _____                                        |                         |                                              |                  |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |                         | DATE: _____ DATE COMPLETED <u>7-19-12</u>    |                  |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |                         | MECHANIC <u>James</u>                        |                  |  |
| SMOKES SHORTED VIBRATE OTHER _____                 |                         | JOB NAME/LOCATION <u>Franklin Ky</u>         | JOB NUMBER _____ |  |
| PROBLEM: <u>Bad battery</u>                        |                         |                                              |                  |  |
| REPAIRED: <u>replaced both batteries</u>           |                         |                                              |                  |  |
| PARTS: <u>2 - 40 Batteries 305.00 Advance</u>      |                         |                                              |                  |  |

EQUIPMENT  
REPAIRS

DATE 5-30-14

MILEAGE/HOURS 4500 HRS

EQUIPMENT REPAIRED #1006 Komatsu Wm300-1

REPAIRS MADE Serviced

HOURS WORKED \_\_\_\_\_

PARTS USED

All but on ster filter \$479.<sup>26</sup>  
Filter steel \$74.<sup>00</sup>

Ten Filter Jals  
White Horse Equipment

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|---------------|-------------|-------------------------------|--|------------------------------|--------------|--------------|---------------------------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1006</u><br>MAKE <u>Komatsu</u><br>MODEL <u>Hm300-1</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____                                                                                                                                                                                                                                                                                                                      | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE   HYDRAULIC   ENGINE   IMPLEMENTS<br>POWER TRAIN   ELECTRIC   DRIVE TRAIN   UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT   REAR   LEFT   RIGHT   UPPER   LOWER<br>OTHER _____                                       |                         |               |             |                               |  |                              |              |              |                                 |
| REASON FOR FAILURE:   BROKEN   WORN   ABUSE   LOOSE   SEIZED<br>OVERHEAT   PLANNED   CONTAM   LEAKING   NOISY   SCRATCH<br>SMOKES   SHORTED   VIBRATE   OTHER _____                                                                                                                                                                                                                                                                                                           |                                                                                                               | DATE: <u>1-14-14</u> DATE COMPLETED <u>1-14-15</u><br>MECHANIC <u>JAMES</u><br><table style="width: 100%; border: none;"> <tr> <td style="border: none; width: 70%;">JOB NAME/LOCATION</td> <td style="border: none; width: 30%;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION       | JOB NUMBER    |             |                               |  |                              |              |              |                                 |
| JOB NAME/LOCATION                                                                                                                                                                                                                                                                                                                                                                                                                                                             | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
| PROBLEM: <u>left suspension cylinder down</u>                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                                                                                               |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
| REPAIRED: <u>replaced bushings and seals</u>                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                               |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |
| <table style="width: 100%; border: none;"> <tr> <td style="width: 33%;">PARTS: <u>Fan belts</u></td> <td style="width: 33%; text-align: center;"><u>122.39</u></td> <td style="width: 33%; text-align: center;"><u>NAPA</u></td> </tr> <tr> <td><u>Bushings &amp; O-rings</u></td> <td></td> <td><u>White Horse Equipment</u></td> </tr> <tr> <td><u>Seals</u></td> <td style="text-align: center;"><u>82.96</u></td> <td><u>Signal industrial supply</u></td> </tr> </table> |                                                                                                               |                                                                                                                                                                                                                                                                  | PARTS: <u>Fan belts</u> | <u>122.39</u> | <u>NAPA</u> | <u>Bushings &amp; O-rings</u> |  | <u>White Horse Equipment</u> | <u>Seals</u> | <u>82.96</u> | <u>Signal industrial supply</u> |
| PARTS: <u>Fan belts</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <u>122.39</u>                                                                                                 | <u>NAPA</u>                                                                                                                                                                                                                                                      |                         |               |             |                               |  |                              |              |              |                                 |
| <u>Bushings &amp; O-rings</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                                                                                               | <u>White Horse Equipment</u>                                                                                                                                                                                                                                     |                         |               |             |                               |  |                              |              |              |                                 |
| <u>Seals</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <u>82.96</u>                                                                                                  | <u>Signal industrial supply</u>                                                                                                                                                                                                                                  |                         |               |             |                               |  |                              |              |              |                                 |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                          |                                           | EQUIPMENT DOWNTIME                                    | COMPONENT CODES                                    |            |
|----------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------|----------------------------------------------------|------------|
| EQUIP. # <u>1066</u>                                           | REASON<br>PARTS      LABOR<br>OTHER _____ | HOURS _____ DAYS _____                                | BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS |            |
| MAKE <u>Komatsu</u>                                            |                                           | POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED |                                                    |            |
| MODEL <u>Hm300-1</u>                                           |                                           | COMPONENT LOCATION                                    |                                                    |            |
| SERIAL # _____                                                 |                                           | FRONT    REAR    LEFT    RIGHT    UPPER    LOWER      |                                                    |            |
| HOUR METER _____                                               |                                           |                                                       | OTHER _____                                        |            |
| MILES _____                                                    |                                           |                                                       |                                                    |            |
| REASON FOR FAILURE: BROKEN    WORN    ABUSE    LOOSE    SEIZED |                                           |                                                       | DATE: _____ DATE COMPLETED <u>9-2-15</u>           |            |
| OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH   |                                           |                                                       | MECHANIC <u>JAMES &amp; STEVEN</u>                 |            |
| SMOKES    SHORTED    VIBRATE    OTHER _____                    |                                           |                                                       | JOB NAME/LOCATION<br><u>Shop</u>                   | JOB NUMBER |
| PROBLEM: <u>Epc Bad</u>                                        |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
| REPAIRED: <u>replaced Epc &amp; one hose</u>                   |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
| PARTS: <u>Epc</u> <u>1350.00</u> <u>White Horse Equipment</u>  |                                           |                                                       |                                                    |            |
| <u>hose</u> <u>63.09</u> <u>Napa</u>                           |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |
|                                                                |                                           |                                                       |                                                    |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|---------------|------------------------|---------------------|-----------------|------------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1006</u><br>MAKE <u>Komatsu</u><br>MODEL <u>HM300-1</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____                                                                                                                                   | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____                                                                                            |                                  |               |                        |                     |                 |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                                                                                                                                                  |                                                                                                               | DATE: _____ DATE COMPLETED <u>2-10-16</u><br>MECHANIC <u>JAMES</u><br><table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; padding: 2px;">JOB NAME/LOCATION<br/><u>Cato</u></td> <td style="width: 50%; padding: 2px;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>Cato</u> | JOB NUMBER    |                        |                     |                 |                  |
| JOB NAME/LOCATION<br><u>Cato</u>                                                                                                                                                                                                                                                           | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
| PROBLEM: <u>won't start fuel bleeding back</u>                                                                                                                                                                                                                                             |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
|                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
| REPAIRED: <u>replaced hand primer pump.</u><br><u>cleaned fuel cap</u><br><u>changed fuel filters</u>                                                                                                                                                                                      |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
|                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |
| <table style="width: 100%;"> <tr> <td style="width: 33%;">PARTS: <u>Pump</u></td> <td style="width: 33%;"><u>119.24</u></td> <td style="width: 33%;"><u>Power Equipment</u></td> </tr> <tr> <td><u>Fuel Filters</u></td> <td><u>in stock</u></td> <td><u>Km Filter</u></td> </tr> </table> |                                                                                                               |                                                                                                                                                                                                                                                                                                 | PARTS: <u>Pump</u>               | <u>119.24</u> | <u>Power Equipment</u> | <u>Fuel Filters</u> | <u>in stock</u> | <u>Km Filter</u> |
| PARTS: <u>Pump</u>                                                                                                                                                                                                                                                                         | <u>119.24</u>                                                                                                 | <u>Power Equipment</u>                                                                                                                                                                                                                                                                          |                                  |               |                        |                     |                 |                  |
| <u>Fuel Filters</u>                                                                                                                                                                                                                                                                        | <u>in stock</u>                                                                                               | <u>Km Filter</u>                                                                                                                                                                                                                                                                                |                                  |               |                        |                     |                 |                  |
|                                                                                                                                                                                                                                                                                            |                                                                                                               |                                                                                                                                                                                                                                                                                                 |                                  |               |                        |                     |                 |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 1006

MAKE Komatsu

MODEL WP300-1

SERIAL # \_\_\_\_\_

HOUR METER \_\_\_\_\_

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS

LABOR

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 4-9-16

MECHANIC JAMES

JOB NAME/LOCATION

CAFO

JOB NUMBER

PROBLEM: blown hose

REPAIRED: replaced left dump cylinder hose

PARTS: hose

64.64

Nashville Rubber & Basket

EQUIPMENT  
REPAIRS

DATE 4-2-16

MILEAGE/HOURS 5K HRS

EQUIPMENT REPAIRED #1006 Komatsu HM300

REPAIRS MADE Serviced

HOURS WORKED \_\_\_\_\_

PARTS USED

All Filters

540<sup>00</sup>

Tenn Filter

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                          |                                                                                 | EQUIPMENT DOWNTIME                                    | COMPONENT CODES |  |
|----------------------------------------------------------------|---------------------------------------------------------------------------------|-------------------------------------------------------|-----------------|--|
| EQUIP. # <u>1006</u>                                           | HOURS _____ DAYS _____<br><br>REASON<br><br>PARTS      LABOR<br><br>OTHER _____ | BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS    |                 |  |
| MAKE <u>Komatsu</u>                                            |                                                                                 | POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED |                 |  |
| MODEL <u>HM300-1</u>                                           |                                                                                 | COMPONENT LOCATION                                    |                 |  |
| SERIAL # _____                                                 |                                                                                 | FRONT    REAR    LEFT    RIGHT    UPPER    LOWER      |                 |  |
| HOUR METER _____                                               |                                                                                 | OTHER _____                                           |                 |  |
| MILES _____                                                    |                                                                                 | _____                                                 |                 |  |
| REASON FOR FAILURE: BROKEN    WORN    ABUSE    LOOSE    SEIZED |                                                                                 | DATE: <u>9-13-16</u> DATE COMPLETED _____             |                 |  |
| OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH   |                                                                                 | MECHANIC _____                                        |                 |  |
| SMOKES    SHORTED    VIBRATE    OTHER _____                    |                                                                                 | JOB NAME/LOCATION                                     | JOB NUMBER      |  |

PROBLEM: \_\_\_\_\_

REPAIRED: replaced seal & bushing in left front  
suspension cylinder  
Serviced  
rim bolts

|                                           |                                     |                                         |
|-------------------------------------------|-------------------------------------|-----------------------------------------|
| <u>All Filters but steer</u>              | <u>421.<sup>00</sup></u>            | <u>Tenn Filter</u>                      |
| <u>bushings</u>                           | <u>178.<sup>00</sup></u>            | <u>Power Equipment</u>                  |
| <u>seals</u>                              | <u>53.<sup>00</sup></u>             | <u>Signal</u>                           |
| <u>bolts</u>                              | <u>\$60.<sup>00</sup></u>           | <u>Thompson</u>                         |
| <u><del>4-11-16</del> <del>1005</del></u> | <u><del>178.<sup>00</sup></del></u> | <u><del>White Horse Equipment</del></u> |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|----------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>300-1 #1006</u>                        |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>Komatsu</u>                                |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>HM300-1</u>                               |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # <u>1006</u>                               |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                   |  |                         | OTHER _____                                  |                  |
| MILES _____                                        |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: <u>11-9-16</u> DATE COMPLETED _____    |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>St CB &amp; P</u>                |                  |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION <u>Home &amp; suites</u>   | JOB NUMBER _____ |
| PROBLEM: <u>REPLACED 2 FUEL HOSES</u>              |  |                         |                                              |                  |
| <u>FIXED BROKEN BOLT</u>                           |  |                         |                                              |                  |
| <u>&amp; HAND FUEL PUMP.</u>                       |  |                         |                                              |                  |
| REPAIRED: <u>COST - \$475.07</u>                   |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
| PARTS: _____                                       |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |
|                                                    |  |                         |                                              |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                               |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|-----------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1005</u>                                |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                 |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>Hm300-1</u>                                |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                      |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER <u>600 HRS</u>                           |  |                         | OTHER _____                                  |            |
| MILES _____                                         |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  |  |                         | DATE: <u>3-7-17</u> DATE COMPLETED _____     |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH       |  |                         | MECHANIC _____                               |            |
| SMOKES SHORTED VIBRATE OTHER _____                  |  |                         | JOB NAME/LOCATION                            | JOB NUMBER |
| PROBLEM: <u>need serviced</u>                       |  |                         |                                              |            |
| REPAIRED: <u>serviced</u>                           |  |                         |                                              |            |
| PARTS: <u>All Filters 509, 28 Tenn Filter sales</u> |  |                         |                                              |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                   |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|---------------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1203 (1006)</u>                             |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                     |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>HM300-1</u>                                    |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                          |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                        |  |                         | OTHER _____                                  |            |
| MILES _____                                             |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED      |  |                         | DATE: _____ DATE COMPLETED <u>11-22-17</u>   |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH           |  |                         | MECHANIC <u>Steven B.</u>                    |            |
| SMOKES SHORTED VIBRATE OTHER _____                      |  |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |
| PROBLEM: <u>Service</u>                                 |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
| REPAIRED: <u>Serviced</u>                               |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
| PARTS: <u>Filters</u> <u>481.98</u> <u>Term Filter</u>  |  |                         |                                              |            |
| <u>Steel Filter</u> <u>80.00</u> <u>Power Equipment</u> |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |
|                                                         |  |                         |                                              |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|----------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1203</u>                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>Hm300-1</u>                               |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                  |            |
| MILES _____                                        |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: _____ DATE COMPLETED <u>2-1-18</u>     |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>Steven B.</u>                    |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>Shop</u>             | JOB NUMBER |
| PROBLEM: <u>old batteries</u>                      |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
| REPAIRED: <u>replaced both batteries</u>           |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
| PARTS: <u>2- 4D-XHD</u> <u>398.85</u> <u>IRS</u>   |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


| EQUIPMENT INFORMATION                                                  |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|------------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1203</u>                                                   |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>Komatsu</u>                                                    |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>HM300-1</u>                                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                                         |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                                       |  |                         | OTHER _____                                  |                  |
| MILES _____                                                            |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                     |  |                         | DATE: _____ DATE COMPLETED <u>3-17-18</u>    |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                          |  |                         | MECHANIC <u>All</u>                          |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                     |  |                         | JOB NAME/LOCATION <u>Shop</u>                | JOB NUMBER _____ |
| PROBLEM: <u>left steer cylinder leaking</u>                            |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
| REPAIRED: <u>packed cylinder</u>                                       |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
| PARTS: <u>seal kit</u> <u>270.<sup>00</sup></u> <u>Power Equipment</u> |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |
|                                                                        |  |                         |                                              |                  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                                         |                                                                                                                                      |                                                                                                                                                                                                                                                                               |                                     |            |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|------------|
| <p><b>EQUIPMENT INFORMATION</b></p> <p>EQUIP. # <u>1203</u></p> <p>MAKE <u>Komatsu</u></p> <p>MODEL <u>HM300-1</u></p> <p>SERIAL # _____</p> <p>HOOR METER _____</p> <p>MILES _____</p> | <p><b>EQUIPMENT DOWNTIME</b></p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p> | <p><b>COMPONENT CODES</b></p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p><b>COMPONENT LOCATION</b></p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>                                               |                                     |            |
| <p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p>                                |                                                                                                                                      | <p>DATE: _____ DATE COMPLETED <u>6-15-18</u></p> <p>MECHANIC <u>Charles</u></p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION<br/><u>Cargill</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>Cargill</u> | JOB NUMBER |
| JOB NAME/LOCATION<br><u>Cargill</u>                                                                                                                                                     | JOB NUMBER                                                                                                                           |                                                                                                                                                                                                                                                                               |                                     |            |
| <p>PROBLEM: <u>blown hose at hitch</u></p> <p>_____</p> <p>_____</p>                                                                                                                    |                                                                                                                                      |                                                                                                                                                                                                                                                                               |                                     |            |
| <p>REPAIRED: <u>replaced hose</u></p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>                                                                     |                                                                                                                                      |                                                                                                                                                                                                                                                                               |                                     |            |
| <p>PARTS: _____</p> <p><u>Hose</u> <u>367.8P</u> <u>Nashville Rubber Binslet</u></p> <p>_____</p> <p>_____</p> <p>_____</p>                                                             |                                                                                                                                      |                                                                                                                                                                                                                                                                               |                                     |            |



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |                                | EQUIPMENT DOWNTIME                           | COMPONENT CODES                                                       |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|----------------------------------------------|-----------------------------------------------------------------------|--|
| EQUIP. # <u>1203</u>                                                                                                                      | REASON<br>PARTS LABOR<br>OTHER | HOURS _____ DAYS _____                       | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                             |  |
| MAKE <u>Komatsu</u>                                                                                                                       |                                | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                                                                       |  |
| MODEL <u>HM300-1</u>                                                                                                                      |                                | COMPONENT LOCATION                           |                                                                       |  |
| SERIAL # _____                                                                                                                            |                                | FRONT REAR LEFT RIGHT UPPER LOWER            |                                                                       |  |
| HOUR METER <u>7K mis</u>                                                                                                                  |                                | OTHER _____                                  |                                                                       |  |
| MILES _____                                                                                                                               |                                |                                              |                                                                       |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |                                |                                              | DATE: _____ DATE COMPLETED <u>10-19-18</u><br>MECHANIC <u>Charles</u> |  |
| PROBLEM: <u>Needs serviced</u>                                                                                                            |                                |                                              | JOB NAME/LOCATION <u>Beckwith</u> JOB NUMBER _____                    |  |
| REPAIRED: _____                                                                                                                           |                                |                                              |                                                                       |  |
| PARTS: <u>All F. Hens</u> <u>516.04</u> <u>Tenn Filter sales</u>                                                                          |                                |                                              |                                                                       |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                          |  |                                                                                                               |  |                                                                                                                                                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1203</u><br>MAKE <u>Komatsu</u><br>MODEL <u>HM300-1</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____ |  | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ |  | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br>COMPONENT LOCATION<br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____ |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                |  |                                                                                                               |  | DATE: _____ DATE COMPLETED <u>11-7-18</u><br>MECHANIC <u>Charles</u><br>JOB NAME/LOCATION <u>Maple Crossing</u> JOB NUMBER _____                                                              |  |
| PROBLEM: <u>broken door handle</u>                                                                                                                       |  |                                                                                                               |  |                                                                                                                                                                                               |  |
| REPAIRED: <u>replaced driver door handle + cover</u><br><u>replaced driver spot mirror</u>                                                               |  |                                                                                                               |  |                                                                                                                                                                                               |  |
| PARTS: <u>Handle + cover</u> <u>131.60</u> <u>Power Equipment</u><br><u>mirror</u> <u>?</u> <u>White Horse Equipment</u>                                 |  |                                                                                                               |  |                                                                                                                                                                                               |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                                        |                                                                                                               |                                                                                                                                                                                                                                                                                                         |                                 |            |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1203</u><br>MAKE <u>Komatsu</u><br>MODEL <u>Hm300 Trunk</u><br>SERIAL # _____<br>HOUR METER <u>7600 HRS</u><br>MILES _____ | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____                                                                                                    |                                 |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                              |                                                                                                               | DATE <u>5-20-19</u> DATE COMPLETED <u>7-1-19</u><br>MECHANIC <u>Charles</u><br><table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 70%; padding: 2px;">JOB NAME/LOCATION<br/><u>MCH</u></td> <td style="width: 30%; padding: 2px;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>MCH</u> | JOB NUMBER |
| JOB NAME/LOCATION<br><u>MCH</u>                                                                                                                                        | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                                                         |                                 |            |
| PROBLEM: <u>needs service</u>                                                                                                                                          |                                                                                                               |                                                                                                                                                                                                                                                                                                         |                                 |            |
| REPAIRED: <u>serviced</u>                                                                                                                                              |                                                                                                               |                                                                                                                                                                                                                                                                                                         |                                 |            |
| PARTS: <u>All Filters</u> <u>603.12</u> <u>new Filter</u>                                                                                                              |                                                                                                               |                                                                                                                                                                                                                                                                                                         |                                 |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                             |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                               |
|-------------------------------------------------------------------|--|-------------------------|----------------------------------------------|-------------------------------|
| EQUIP. # <u>1203</u>                                              |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                               |
| MAKE <u>Komatsu</u>                                               |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                               |
| MODEL <u>HM300-1</u>                                              |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                               |
| SERIAL # <u>Truck</u>                                             |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                               |
| HOUR METER _____                                                  |  |                         | OTHER _____                                  |                               |
| MILES _____                                                       |  |                         |                                              |                               |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                |  |                         | DATE: <u>7-26-19</u>                         | DATE COMPLETED <u>7-29-19</u> |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                     |  |                         | MECHANIC <u>Bryan</u>                        |                               |
| SMOKES SHORTED VIBRATE OTHER _____                                |  |                         | JOB NAME/LOCATION <u>Ashtland Farms</u>      | JOB NUMBER _____              |
| PROBLEM: <u>leaking hoses</u>                                     |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
| REPAIRED: <u>replaced hoses</u>                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
| PARTS: <u>1-Hose</u> <u>161.43</u> <u>Nashville Rubber Gasket</u> |  |                         |                                              |                               |
| <u>1-Hose</u> <u>187.27</u> <u>Power Equipment</u>                |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |
|                                                                   |  |                         |                                              |                               |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                         |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                    |                  |
|-------------------------------------------------------------------------------|--|-------------------------|----------------------------------------------------|------------------|
| EQUIP. # <u>1203</u>                                                          |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS          |                  |
| MAKE <u>Komatsu</u>                                                           |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED       |                  |
| MODEL <u>HM300-1</u>                                                          |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                 |                  |
| SERIAL # _____                                                                |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                  |                  |
| HOUR METER <u>8K HRS</u>                                                      |  |                         | OTHER _____                                        |                  |
| MILES _____                                                                   |  |                         |                                                    |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                            |  |                         | DATE: <u>11-1-19</u> DATE COMPLETED <u>11-4-19</u> |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                 |  |                         | MECHANIC <u>All</u>                                |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                            |  |                         | JOB NAME/LOCATION <u>Jones Brummett</u>            | JOB NUMBER _____ |
| PROBLEM: <u>Service</u>                                                       |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
| REPAIRED: <u>serviced</u>                                                     |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
| PARTS: <u>All Filters</u> <u>\$556.<sup>52</sup></u> <u>Tenn Filter sales</u> |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |
|                                                                               |  |                         |                                                    |                  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                  |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|------------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1203</u>                                                   |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Komatsu</u>                                                    |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>HM300-1</u>                                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                                         |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                                       |  |                         | OTHER _____                                  |            |
| MILES _____                                                            |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                     |  |                         | DATE: _____ DATE COMPLETED _____             |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                          |  |                         | MECHANIC _____                               |            |
| SMOKES SHORTED VIBRATE OTHER _____                                     |  |                         | JOB NAME/LOCATION                            | JOB NUMBER |
| PROBLEM: <u>Hood latch &amp; striker worn out.</u>                     |  |                         |                                              |            |
| REPAIRED: _____                                                        |  |                         |                                              |            |
| PARTS: <u>latch &amp; striker</u> <u>349.48</u> <u>Power Equipment</u> |  |                         |                                              |            |