

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
MP. # <u>0022</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
KEY <u>Rhevy</u>	REASON _____	COMPONENT LOCATION		FRONT REAR LEFT RIGHT UPPER LOWER	
REL <u>23 2500 HR</u>	PARTS _____ LABOR _____	OTHER _____		OTHER _____	
IAL # _____	OTHER _____	DATE: _____ DATE COMPLETED <u>7-18-25</u>		MECHANIC <u>Ben</u>	
OUR METER _____	ES <u>55k mi</u>	SON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		ERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	
OKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>JHop</u>		JOB NUMBER _____	
BLEM: <u>Service, needs brakes</u>					
PAIRED: <u>Serviced, replaced front and rear pads.</u>					
RTS: <u>pads</u> <u>120.00</u> <u>Advance Auto Parts</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0022</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chery</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>23' 2500 HD</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-1-25</u> DATE COMPLETED <u>12-3-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>To Shop</u>	

PROBLEM: Fan clutch bearing bad.

REPAIRED: replaced fan clutch.

PARTS: fan clutch 505.16 Freeland Chery

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0022</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cherz</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>23' 3500HD</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>New</u>			OTHER _____	
MILES <u>31 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>5-30-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>shop</u>		
PROBLEM: <u>set up for Malachi</u>		JOB NUMBER _____		

REPAIRED: set up truck

PARTS: <u>MATs</u>	<u>103.¹⁴</u>	<u>TSC</u>
<u>safety light</u>	<u>315.⁰⁰</u>	<u>Truckers lighthouse</u>
<u>Power inverter & breaker</u>	<u>300.⁰⁰</u>	<u>Amazon</u>
<u>cable</u>	<u>54.⁰⁰</u>	<u>Amazon</u>
<u>Wife Vice</u>	<u>80.⁰⁰</u>	<u>Lowes</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0022</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chevy</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>23' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>40k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10/31/24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charlie's Tire</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Charlie's Tire</u>	JOB NUMBER
PROBLEM: <u>Serviced and needs tires</u>				
REPAIRED: _____				
PARTS: <u>4- LT245/75-17 Transforce 1/64.67 Charlie's Tire</u>				

1 E O

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0022</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
MAKE <u>Chevy</u>				
MODEL <u>23' 250w</u>				
SERIAL # _____				
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>5-22-25</u> MECHANIC <u>Bryan</u> JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____		
PROBLEM: <u>1 bad battery</u>				
REPAIRED: <u>replaced both batteries</u>				
PARTS: <u>2-4FH6 batteries</u> <u>392.69</u> <u>Advance Auto Parts</u>				